

1/19

FIG. 1




FIG. 1A





FIG. 1B



2/19

FIG. 2




FIG. 2A




FIG. 2B








FIG. 2C








15 16 13 6 9 12 12














FIG. 5




FIG. 5A






FIG. 5B








FIG. 7




FIG. 7A





FIG. 7B



8/19

FIG. 8




FIG. 8A




FIG. 8B





FIG. 8C



9/19

FIG. 9




FIG. 9A





FIG. 9B



10/19

FIG. 10




FIG. 11




FIG. 12





FIG. 13



12/19

FIG. 14




FIG. 14A





FIG. 14B



13/19




FIG. 15A

62

41

56

58

57




FIG. 16





FIG. 16A



15/19

FIG. 17




FIG. 18




FIG. 19





FIG. 20






FIG. 22A 208 --210 EMR Source -224 SCAN CONTROL 218 CONTROL -212 DETECTOR 215 216 - 220 202 000 206 200 214 -204

FIG. 22B

